

Originator : PHONG DO
Planner : JIMMIE KNAPP
Drawing No : 2TGA-M2079
Equip No/Cat: 2TGA--1 3
Project ID : 2TGA-TRB-1
Shutdown : N No Shutdown
Ref No :
Schedule Date :
Priority : 3A
Clearance : NO
Tag Request :
Text ID :
Frequency : NOT SCHEDULED
Last Reading : No Reading

Date Completed: _____ Failure Code: _____
Completed By : _____ Signature : _____
Accepted By : _____ Signature : _____

**** Delay Codes Legend ****
W=Whse C=CrSp T=Tag TL=Tool P=Plan
**** Record Time Daily ****
Delays
Code/Hrs

Step	Job Scope	MN	DY	Safety and Additional Information	Emp No	Date	Hours	Delays Code/Hrs
1	SELECT TWO THERMOCOUPLES FROM EXISTING STOCK TO GET A MATCHED PAIR, AS CLOSE AS POSSIBLE. 1690.06304 (X8) ***** JOB SCOPE: 1. DISCUSS THE WORK TO BE DONE WITH THE UNIT OPERATOR. INFORM HIM OF ANY PROBLEMS WITH ALARMS, CONTROLS, OR INDICATIONS THAT MAY OCCUR AS A RESULT OF THIS WORK. 2. OBTAIN ALL OF THE THERMOCOUPLES FROM STOCK SO THEY CAN BE TESTED. 3. DETERMINE BY TEST, THE TWO THERMOCOUPLES THAT MOST CLOSELY MATCH OUTPUTS FROM 100 DEGREES THROUGH 1000 DEGREES F. 4. THESE TWO WILL BE INSTALLED ON THE OUTER SHELL OF THE HP SECTION OF THE MAIN TURBINE DURING UNIT COOLDOWN. PROBABLY SOMETIME SUNDAY AFTERNOON. 5. RETURN THE OTHER THERMOCOUPLES TO THE WAREHOUSE SO THEY CAN BE RETURNED TO STOCK. 6. THE TWO MATCHED THERMOCOUPLES SHOULD BE GIVEN TO HOWARD SCOTT FOR INSTALLATION AFTER THE HP SECTION HAS COOLED. IRWIN WILL BE INSTALLING THEM WHEN THE OUTER SHELL SURFACE TEMPERATURE IS BETWEEN 300 AND 400 DEGREES.	1	1	***** SAFETY / ENVIRONMENTAL REQUIREMENTS: A. WEAR PROTECTIVE GLOVES SUITABLE FOR HANDLING HIGH TEMPERATURE METAL. DO NOT SIT THE HOT THERMOCOUPLES DOWN WHERE THEY CAN BE TOUCHED BY ANYONE WHILE THEY ARE COOLING. ***** ADDITIONAL INFORMATION: a. THE THERMOCOUPLES ARE STOCK NUMBER 57539. THERE ARE SEVEN AVAILABLE IN THE WAREHOUSE. THEY SHOULD ALL BE CHECKED OUT SO THEY CAN BE COMPARED. RETURN THE ONES NOT USED TO THE WAREHOUSE.				

**** IMPORTANT NOTICE ****
YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



01-19846-8

IP7_005512

Step	Job Scope Cont'd	MN	DY	Safety and Additional Information Cont'd	Notes Cont'd:
1	7. PLEASE NOTE ALL PROBLEMS FOUND AND ANY CORRECTIVE ACTION TAKEN TO RETURN THE SYSTEM TO NORMAL OPERATION.				

IP7_005513

** Work Order Parts List **							
Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1 57539	THERMOCOUPLE, TYPE E	S 206075	03/02/02	EA	5	0	5

IP7_005514